

**From:** [Wright, Jeff](#)  
**To:** [Gary Moore/R6/USEPA/US@EPA](#)  
**Subject:** RE: Delta Shipyards  
**Date:** 10/04/2012 01:07 PM  
**Attachments:** [Delta\\_FOC\\_Ind.xlsx](#)  
[Delta\\_Waste\\_120925\\_R1.xlsx](#)  
[Delta\\_Waste\\_121004\\_RMLs.xlsx](#)

---

Our GIS person is out. Let me check with Houston and Dallas. When do you need these maps?

Mark compiled some summary table, which I've attached for your review. One contains the extent of contamination sample points and the other two are Pit/waste sample results, one of which is just RMLs.



**Jeff Wright, CHMM**  
**Weston Solutions, Inc.**  
*an employee-owned company*  
13702 Coursey Blvd.,  
Bldg #7, STE A  
Baton Rouge, LA 70817  
(225) 297-5415 Direct  
(225) 278-8406 Cell  
[Jeff.Wright@westonsolutions.com](mailto:Jeff.Wright@westonsolutions.com)

---

**From:** Gary Moore [<mailto:Moore.Gary@epamail.epa.gov>]  
**Sent:** Thursday, October 04, 2012 12:41 PM  
**To:** Wright, Jeff  
**Subject:** Delta Shipyards

Jeff:

Can you guys produce a map that shows where the contamination is based upon the EPA RSLs and the LA Recap. Both Industrial. You will probably have to show it as a krieging analysis based upon the sampling depths. At some point we may want to do a 3 D but you guys will have to let me know what you can do.

Thanks

Gary Moore  
Federal On-Scene Coordinator  
EPA Region 6  
Cell: 214-789-1627  
Work: 214-665-6609  
email: [moore.gary@epa.gov](mailto:moore.gary@epa.gov)

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.



9522450